ASSEMBLY INSTRUCTIONS

FUTON COMPANY

T1 GALN SIDE

①	②	A	B	C
X1	X3	15 PIECES	3 PIECES	3 PIECES



*** Cross head Screwdriver also required assembly**

1.



2.